



Exhibit 4 – Photos of Residence



James M. Wood House, view from street



Existing roof with eyebrow dormer



East elevation with wrapped gable end



Existing garage roof

Exhibit 5 – Proposed Material



Owens Corning, Laminated Composition Shingles, Chateau Green (or similar)



Example of shingle appearance