

Harada House Structural Engineering Assessment Work November 2017



Termite and dry rot damaged floor beam
(supports front wall of Harada House)



Termite damaged stud at window header,
East Elevation



Dry rot damaged floor joist, South Elevation



Dry rot damaged floor joist at South Elevation –
located at connection of dining room and kitchen



Evidence of termite activity
Floor joist at South Elevation