

Exhibit 3 – Current Photos



Figure 1 - North (front) elevation, view from street



Figure 2 - North (front) elevation

Exhibit 3 – Current Photos



Figure 3 - North (front) Elevation



Figure 4 - North (front) Elevation

Exhibit 3 – Current Photos



Figure 5 - Front Steps



Figure 6 - Main Entry

Exhibit 3 – Current Photos



Figure 7 - Front Porch



Figure 8 - Front Window (example)

Exhibit 3 – Current Photos



Figure 9 - Side (West) Elevation



Figure 10 - Northeast corner with wrap around porch

Exhibit 3 – Current Photos



Figure 11 - Side (East) Elevation



Figure 12 - Rear of the property, view looking north

Exhibit 3 – Current Photos



Figure 13 - Enclosed carport, dated 1969



Figure 14 - South and east elevation, with 1973 two-story addition

Exhibit 3 – Current Photos



Figure 15 - East elevation, 1973 two-story addition



Figure 16 - Interior photo

Exhibit 3 – Current Photos



Figure 17 - Interior photo



Figure 18 - Interior photo

Exhibit 3 – Current Photos



Figure 19 - Interior photo