

Exhibit 3 – Current Photos



Figure 1 – Edie street view highlighting orientation to the street, view southeast



Figure 2 – Edie façade, secondary front elevation, and driveway, view east/southeast

Exhibit 3 – Current Photos



Figure 3 – Edie façade entry, view south/southwest



Figure 4 – Edie façade fenestration, eave, and roof beams behind freestanding garden wall, view southwest

Exhibit 3 – Current Photos



Figure 5 – Interior view of façade fenestration and continuation of open beam and ceiling boards, view northeast



Figure 6 – Rear elevation, view northeast

Exhibit 3 – Current Photos



Figure 7 – Sheltered, central patio with steps to sunken carport (left), view north/northeast



Figure 8 – East side/rear elevation showing small patio behind secondary front elevation block wall, view southwest

Exhibit 3 – Current Photos



Figure 9 – Rear and east side/rear elevation showing example of double-hung vinyl replacement of jalousie window in original opening, view northwest