

## Site Photos



**Figure 1 - View from Arlington Avenue**



**Figure 2 - South and East Elevations**



## Site Photos



**Figure 3 - North and East Elevations**



**Figure 4 - North (Rear) Elevation**



## Site Photos



**Figure 5 - North and West Elevations, including Auto Service Center**



**Figure 6 - South and West Elevations**



## Site Photos



**Figure 7 - Auto Service Center**



**Figure 8 - South (Front) Elevation, from Arlington Avenue**



## Site Photos



**Figure 9 - View from across Arlington Ave**



**Figure 10 - Rear view from across Streeter Avenue**



## Site Photos



Figure 11 - View from Streeter Avenue



Figure 12 - Bird's eye view looking northwest



## Site Photos



**Figure 13 - Bird's eye view looking southwest**



**Figure 14 - Bird's eye view looking southeast**



## Site Photos



Figure 15 - Main floor interior



Figure 16 - Main floor interior



## Site Photos



**Figure 17 - Main floor interior**



**Figure 18 - Main floor interior**



## Site Photos



**Figure 19 - Basement interior**



**Figure 20 - Basement interior**



## Site Photos



Figure 21 - Basement interior



Figure 22 - Basement interior



## Site Photos



**Figure 23 - Basement interior**



**Figure 24 - Basement interior**



## Site Photos



**Figure 25 - Basement interior**



**Figure 26 - Plumbing system damage**



## Site Photos



**Figure 27 - Electrical system damage**



**Figure 28 - Electrical system damage**