

Figure 1 - Postcard of Original Residence, circa 1910




Figure 2 - Main driveway approach with residence and garage, view looking north



Figure 3 - Staircase and facade, view looking northwest



Figure 4 - Facade, view looking west



Figure 5 - Front porch, view looking northeast



Figure 6 - Front porch, view looking southwest



Figure 7 - Front porch, view looking southwest



Figure 8 - Front porch, view looking southeast



Figure 9 - Front porch, view looking northeast



Figure 10 - Rear elevation, view looking southeast



Figure 11 - Rear elevation steps, view looking southeast



Figure 12 - Rear enclosed porch/mud room view looking northeast



Figure 13 - Rear enclosed porch/mud room view looking west




Figure 14 - Main living room, interior view



Figure 15 - Main living room, interior view



Figure 16 - Main living room, interior view



Figure 17 – Interior space



Figure 18 - Garage as seen from the porch



Figure 19 - Garage, view looking west