

Quoted for: City of Riverside, California

Customer Contact:

Phone:

Quoted by: Ryan Hilsabeck

Phone: (816)676-4000 Email: ryan.hilsabeck@altec.com

Altec Account Manager: Matt Hadley

REFERENCE ALTEC MODEL

HLIW1600T	Hotline Insulator Washer	\$108,388
-----------	--------------------------	-----------

Per NJPA Specifications plus Options below

(A.) NJPA OPTIONS ON CONTRACT (Unit)

1		
2		
3		
4		

(A1.) NJPA OPTIONS ON CONTRACT (General)

1		
2		
3		
4		
5		
6		
7		
8		

NJPA OPTIONS TOTAL: \$108,388

(B.) OPEN MARKET ITEMS (Customer Requested)

1	UNIT	Upgrade Engine to Cummins Tier IV Final Rule Engine	\$14,192
2	UNIT	One (1) Spare Wash Gun with 1/4" nozzle	\$1,836
3	UNIT	One (1) Spare 1/4" nozzle	\$295
4	UNIT	One (1) Spare Tire and Wheel	\$2,075
5	MISC	Estimated Sales Tax (7.75%)	\$9,826
6			
7			
8			

OPEN MARKET OPTIONS TOTAL: \$28,224

SUB-TOTAL FOR UNIT/BODY/CHASSIS: \$136,612

Delivery to Customer: \$3,140

TOTAL FOR UNIT/BODY/CHASSIS: \$139,752

(C.) ADDITIONAL ITEMS (items are not included in total above)

1		
2		
3		
4		

****Pricing valid for 45 days****

NOTES

PAINT COLOR: Black

WARRANTY: Standard Altec Warranty - One (1) year parts warranty One (1) year labor warranty Ninety (90) days warranty for travel charges (Mobile Service) Limited Lifetime Structural Warranty. Chassis to include standard warranty, per the manufacturer. (Parts only warranty on mounted equipment for overseas customers)

TO ORDER: To order, please contact the Altec Inside Sales Representative listed above.

CHASSIS: Per Altec Commercial Standard

DELIVERY: No later than 210-240 days ARO, FOB Customer Location

TERMS: Net 30 days

BEST VALUE: Altec boasts the following "Best Value" features: Altec ISO Grip Controls for Extra Protection, Only Lifetime Warranty on Structural Components in Industry, Largest Service Network in Industry (Domestic and Overseas), Altec SENTRY Web/CD Based Training, Dedicated/Direct Gov't Sales Manager, In-Service Training with Every Order.

TRADE-IN: Equipment trades must be received in operational condition (as initial inspection) and DOT compliant at the time of pick-up. Failure to comply with these requirements, may result in customer bill-back repairs.

BUILD LOCATION: Saint Joseph, MO