Mt. Rubidoux—Unpaved Trail Repairs and Erosion Control

Issue: Erosion

- Concentrated water flowing at a high velocity
- Foot traffic tramples vegetation that is needed to protect soil
- Drought reduces vegetation growth




Solution: Redirect foot traffic

- Retaining wall along base of firebreak and segments of fencing to direct foot traffic along switchback trail
- Signage and trail markers to encourage use of switchback trail and discourage use of firebreak
- Reclaim unofficial paths

Solution: Accommodate/ slow down stormwater

- Gabion check dams
- Rock-lined drainage dips



Da		ø
6		
	PROTECT THE PARK	
	STAY ON TRAIL	
	EXTERNAL RESERVED AND CONTINUES AND CARES	
		• J

Toolbox

Barrier options



Gabion/rock check dams & swales







Retaining wall

