

Employee Recognition

Mission Inn Avenue Leak Repair


RiversidePublicUtilities.com

Mission Inn Ave Leak

- July 9, 2015
- 36-inch Transmission Main (1936)
 - Holes caused by corrosion
- Old valves in poor condition
 - Additional valves closed to isolate
 - Pressure drop downtown
 - Press Enterprise needed water to produce paper

RiversidePublicUtilities.com





Mike Perez - Supervisor



Dwayne Slife – Water Operator



Don Hesch - Pipefitter



Erick Shackleford - Pipefitter



• Abe Hurtado - Apprentice



THANK YOU!

RiversidePublicUtilities.com

