

Attachment 1 – Project Photos



Figure 1 - Excavating the pipe



Figure 2 - Repairing the pipe



Figure 6 - Water flowing from leak



Figure 3 - Assessing the damage



Figure 4 – Final pavement on Lyon Ave



Figure 5 - Final pavement on Victoria Ave