



Park and Recreation Commission Report

Public Works Department
Urban Forestry/Landscape Division Quarterly Report

4th Quarter 2016

Claims

Date	Ward	Claim	Status
09/22/2016	3	Root Damage to Driveway, Garage, Outside Wall	Assigned for Investigation
09/27/2016	3	Tree Limb Fell on Vehicle	Denied
09/29/2016	4	Root Damage to Driveway	Assigned for Investigation
10/04/2016	2	Roots in Sewer Lateral Line	Assigned for Investigation
10/07/2016	6	Root Damage to Driveway, Sidewalk, Garage	Assigned for Investigation
10/07/2016	3	Roots in Sewer Lateral Line	Assigned for Investigation
10/11/2016	7	Root Damage to Garage Floor	Assigned for Investigation
10/11/2016	5	Root Damage to Sprinkler System	Assigned for Investigation
10/14/2016	3	Root Damage to Walkway	Assigned for Investigation
10/11/2016	3	Root Damage to Waterline	Assigned for Investigation
10/17/2016	5	Root Damage to Wall and Sewer Laterals	Assigned for Investigation
10/17/2016	4	Debris from City Trees Causing Litter	Denied
10/21/2016	4	Damage to Driveway and Wants a New Tree	Assigned for Investigation
10/21/2016	5	Limb Fell on a Driveway Light	Settled
10/21/2016	3	Root Damage to Sewer Lateral	Assigned for Investigation
10/21/2016	5	Limb Fell on a Vehicle	Denied
10/25/2016	6	Contractor Trimming Tree Broke Mailbox	Assigned to Contractor
10/27/2016	1	Roots Cracking the Driveway	Assigned for Investigation
10/28/2016	2	Roots in Sewer Lateral Line	Assigned for Investigation
11/01/2016	3	Tree Limb Fell on Vehicle	Denied
11/02/2016	4	Vehicle Windshield Broken by Tree Limb	Denied
11/10/2016	4	Root Damage to Garage, Driveway, Sprinklers	Assigned for Investigation
11/15/2016	5	Roots in Sewer Lateral Line	Assigned for Investigation
11/17/2016	3	Limb Fell on House and Car	Denied
11/21/2016	3	Branch Fell on Vehicle Causing Major Damages	Denied
11/23/2016	3	Limb Fell on Vehicle	Denied
11/23/2016	3	Roots in Sewer Lateral Line	Assigned for Investigation
11/23/2016	3	Root Damage to Sprinkler System	Assigned for Investigation
11/29/2016	3	Limb Fell on Vehicle Causing Injuries	Denied
11/30/2016	6	Roots in Sewer Lateral Line	Assigned for Investigation