


5

RiversideCA.gov



 Due to structural condition house deemed a public safety hazard - August 25, 2020 and red-tagged



PATH FORWARD


- Proceed with demolition and reconstruction in accordance with Secretary of the Interior's Standards for the Treatment of Historic Properties
- Reconstruction the most costeffective course of action
- CDBG allocation may not be sufficient






7

PROJECT STAGES Demolition - Since red-tagged, demolition must occur in a timely manner Salvage and documentation - Salvage plan prepared Preparation of laser as-builts is being scheduled - HABS-level photo-documentation Reconstruct to ca. 1930 - Earliest photo-documentation - Midway in Harada House's period of significance 8 **RiversideCA.gov** VERSID







RiversideCA.gov