

Exhibit 8 – Site Photos



Figure 1 - Front facade, view looking southeast



Figure 2 - South elevation, view looking northeast

Exhibit 8 – Site Photos



Figure 3 - South elevation, view looking north



Figure 4 - South and east elevations, view looking northwest

Exhibit 8 – Site Photos



Figure 5 - East and north elevation, view looking southwest



Figure 6 - North elevation, view looking south

Exhibit 8 – Site Photos



Figure 7 - Front facade fire damage



Figure 8 - Front and south side fire damage

Exhibit 8 – Site Photos



Figure 9 - South side fire damage



Figure 10 - South side fire damage

Exhibit 8 – Site Photos



Figure 11 - 4472 Orange St context from across the street, view looking southeast